

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-3/25/2009	Southwest Area (sidewalk bridge level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST2-3/25/2009	Southeast Area (sidewalk bridge level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST4-3/25/2009	Northwest Area (street-level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST5-3/25/2009	Firehouse #10 (roof level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-3/25/2009	North Side Sidewalk Bridge	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST100-3/25/2009	Station 10 Field Duplicate	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST11-3/25/2009	90 Trinity Place (roof level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-3/25/2009	110 Greenwich Street (roof level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-3/25/2009	Marriott Hotel, 38th Floor (roof level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST14-3/25/2009	West Face - South end at corner (scaffolding level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-3/25/2009	South Face - East end at corner (scaffolding level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST16-3/25/2009	East Face - North end at corner (scaffolding level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST17-3/25/2009	North Face - West end at corner (scaffolding level)	3/25/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-3/26/2009	Southwest Area (sidewalk bridge level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	66	No	No	
PM10-ST2-3/26/2009	Southeast Area (sidewalk bridge level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST4-3/26/2009	Northwest Area (street-level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST5-3/26/2009	Firehouse #10 (roof level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST10-3/26/2009	North Side Sidewalk Bridge	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST100-3/26/2009	Station 10 Field Duplicate	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST11-3/26/2009	90 Trinity Place (roof level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST12-3/26/2009	110 Greenwich Street (roof level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST13-3/26/2009	Marriott Hotel, 38th Floor (roof level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST14-3/26/2009	West Face - South end at corner (scaffolding level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST15-3/26/2009	South Face - East end at corner (scaffolding level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST16-3/26/2009	East Face - North end at corner (scaffolding level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST17-3/26/2009	North Face - West end at corner (scaffolding level)	3/26/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	

Note:

1. The PM10 reading from Station 100 (Station 10 Field Duplicate) on March 25, 2009 was not available on account of instrument malfunction.