

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-3/30/2009	Southwest Area (sidewalk bridge level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-3/30/2009	Southeast Area (sidewalk bridge level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST4-3/30/2009	Northwest Area (street-level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST5-3/30/2009	Firehouse #10 (roof level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST10-3/30/2009	North Side Sidewalk Bridge	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST11-3/30/2009	90 Trinity Place (roof level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST12-3/30/2009	110 Greenwich Street (roof level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST13-3/30/2009	Marriott Hotel, 38th Floor (roof level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-3/30/2009	West Face - South end at corner (scaffolding level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST15-3/30/2009	South Face - East end at corner (scaffolding level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST16-3/30/2009	East Face - North end at corner (scaffolding level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST17-3/30/2009	North Face - West end at corner (scaffolding level)	3/30/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-3/31/2009	Southwest Area (sidewalk bridge level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-3/31/2009	Southeast Area (sidewalk bridge level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST4-3/31/2009	Northwest Area (street-level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST5-3/31/2009	Firehouse #10 (roof level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-3/31/2009	North Side Sidewalk Bridge	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-3/31/2009	90 Trinity Place (roof level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST12-3/31/2009	110 Greenwich Street (roof level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-3/31/2009	Marriott Hotel, 38th Floor (roof level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-3/31/2009	West Face - South end at corner (scaffolding level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST15-3/31/2009	South Face - East end at corner (scaffolding level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST16-3/31/2009	East Face - North end at corner (scaffolding level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST17-3/31/2009	North Face - West end at corner (scaffolding level)	3/31/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

The PM10 readings from Station 100 (Station 10 Field Duplicate) on March 30 and 31, 2009 were not available on account of instrument malfunction.