

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM10-ST1-5/24/2006	Southwest Area (sidewalk bridge level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-5/24/2006	Southeast Area (sidewalk bridge level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST4-5/24/2006	Northwest Area (street-level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST5-5/24/2006	Firehouse #10 (roof level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST10-5/24/2006	North Side Sidewalk Bridge	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST100-5/24/2006	Station 10 Field Duplicate	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-5/24/2006	90 Trinity Place (roof level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-5/24/2006	110 Greenwich Street (roof level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-5/24/2006	Marriott Hotel, 38th Floor (roof level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-5/24/2006	West Face - South end at corner (scaffolding level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-5/24/2006	South Face - East end at corner (scaffolding level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-5/24/2006	East Face - North end at corner (scaffolding level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-5/24/2006	North Face - West end at corner (scaffolding level)	5/24/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-5/25/2006	Southwest Area (sidewalk bridge level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST2-5/25/2006	Southeast Area (sidewalk bridge level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST4-5/25/2006	Northwest Area (street-level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-5/25/2006	Firehouse #10 (roof level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST10-5/25/2006	North Side Sidewalk Bridge	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST100-5/25/2006	Station 10 Field Duplicate	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-5/25/2006	90 Trinity Place (roof level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST12-5/25/2006	110 Greenwich Street (roof level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST13-5/25/2006	Marriott Hotel, 38th Floor (roof level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST14-5/25/2006	West Face - South end at corner (scaffolding level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST15-5/25/2006	South Face - East end at corner (scaffolding level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST16-5/25/2006	East Face - North end at corner (scaffolding level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST17-5/25/2006	North Face - West end at corner (scaffolding level)	5/25/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	