

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-6/26/2009	Southwest Area (sidewalk bridge level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST2-6/26/2009	Southeast Area (sidewalk bridge level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST4-6/26/2009	Northwest Area (street-level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST5-6/26/2009	Firehouse #10 (roof level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST10-6/26/2009	North Side Sidewalk Bridge	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST100-6/26/2009	Station 10 Field Duplicate	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	52	No	No	
PM10-ST11-6/26/2009	90 Trinity Place (roof level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST12-6/26/2009	110 Greenwich Street (roof level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST13-6/26/2009	Marriott Hotel, 38th Floor (roof level)	6/26/09	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST1-6/27/2009	Southwest Area (sidewalk bridge level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST2-6/27/2009	Southeast Area (sidewalk bridge level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-6/27/2009	Northwest Area (street-level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-6/27/2009	Firehouse #10 (roof level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST10-6/27/2009	North Side Sidewalk Bridge	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST100-6/27/2009	Station 10 Field Duplicate	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST11-6/27/2009	90 Trinity Place (roof level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST12-6/27/2009	110 Greenwich Street (roof level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST13-6/27/2009	Marriott Hotel, 38th Floor (roof level)	6/27/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST1-6/28/2009	Southwest Area (sidewalk bridge level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST2-6/28/2009	Southeast Area (sidewalk bridge level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-6/28/2009	Northwest Area (street-level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-6/28/2009	Firehouse #10 (roof level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST10-6/28/2009	North Side Sidewalk Bridge	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-6/28/2009	Station 10 Field Duplicate	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST11-6/28/2009	90 Trinity Place (roof level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST12-6/28/2009	110 Greenwich Street (roof level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST13-6/28/2009	Marriott Hotel, 38th Floor (roof level)	6/28/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	