

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-8/28/2009	Southwest Area (sidewalk bridge level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST2-8/28/2009	Southeast Area (sidewalk bridge level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-8/28/2009	Northwest Area (street-level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST5-8/28/2009	Firehouse #10 (roof level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST10-8/28/2009	North Side Sidewalk Bridge	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST100-8/28/2009	Station 10 Field Duplicate	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST11-8/28/2009	90 Trinity Place (roof level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST12-8/28/2009	110 Greenwich Street (roof level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST13-8/28/2009	Marriott Hotel, 38th Floor (roof level)	8/28/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST1-8/29/2009	Southwest Area (sidewalk bridge level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-8/29/2009	Southeast Area (sidewalk bridge level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST4-8/29/2009	Northwest Area (street-level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-8/29/2009	Firehouse #10 (roof level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-8/29/2009	North Side Sidewalk Bridge	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST100-8/29/2009	Station 10 Field Duplicate	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST11-8/29/2009	90 Trinity Place (roof level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST12-8/29/2009	110 Greenwich Street (roof level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST13-8/29/2009	Marriott Hotel, 38th Floor (roof level)	8/29/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-8/30/2009	Southwest Area (sidewalk bridge level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-8/30/2009	Southeast Area (sidewalk bridge level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST4-8/30/2009	Northwest Area (street-level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST5-8/30/2009	Firehouse #10 (roof level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-8/30/2009	North Side Sidewalk Bridge	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST100-8/30/2009	Station 10 Field Duplicate	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-8/30/2009	90 Trinity Place (roof level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST12-8/30/2009	110 Greenwich Street (roof level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST13-8/30/2009	Marriott Hotel, 38th Floor (roof level)	8/30/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	