

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-9/17/2008	Southwest Area (sidewalk bridge level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST2-9/17/2008	Southeast Area (sidewalk bridge level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST5-9/17/2008	Firehouse #10 (roof level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST10-9/17/2008	North Side Sidewalk Bridge	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST100-9/17/2008	Station 10 Field Duplicate	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST11-9/17/2008	90 Trinity Place (roof level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST12-9/17/2008	110 Greenwich Street (roof level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST13-9/17/2008	Marriott Hotel, 38th Floor (roof level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST14-9/17/2008	West Face - South end at corner (scaffolding level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST15-9/17/2008	South Face - East end at corner (scaffolding level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST16-9/17/2008	East Face - North end at corner (scaffolding level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST17-9/17/2008	North Face - West end at corner (scaffolding level)	9/17/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-9/18/2008	Southwest Area (sidewalk bridge level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-9/18/2008	Southeast Area (sidewalk bridge level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST4-9/18/2008	Northwest Area (street-level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST5-9/18/2008	Firehouse #10 (roof level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST10-9/18/2008	North Side Sidewalk Bridge	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-9/18/2008	Station 10 Field Duplicate	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST11-9/18/2008	90 Trinity Place (roof level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST12-9/18/2008	110 Greenwich Street (roof level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST13-9/18/2008	Marriott Hotel, 38th Floor (roof level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-9/18/2008	West Face - South end at corner (scaffolding level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST15-9/18/2008	South Face - East end at corner (scaffolding level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST16-9/18/2008	East Face - North end at corner (scaffolding level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST17-9/18/2008	North Face - West end at corner (scaffolding level)	9/18/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	

Note:

1. The PM 10 reading from Station 4 (Northwest Area [street-level]) on September 17, 2008 was not available on account of instrument malfunction.