

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-11/2/2007	Southwest Area (sidewalk bridge level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST2-11/2/2007	Southeast Area (sidewalk bridge level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-11/2/2007	Northwest Area (street-level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST5-11/2/2007	Firehouse #10 (roof level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST10-11/2/2007	North Side Sidewalk Bridge	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST100-11/2/2007	Station 10 Field Duplicate	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST11-11/2/2007	90 Trinity Place (roof level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-11/2/2007	110 Greenwich Street (roof level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST13-11/2/2007	Marriott Hotel, 38th Floor (roof level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-11/2/2007	West Face - South end at corner (scaffolding level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-11/2/2007	South Face - East end at corner (scaffolding level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-11/2/2007	East Face - North end at corner (scaffolding level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST17-11/2/2007	North Face - West end at corner (scaffolding level)	11/2/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-11/3/2007	Southwest Area (sidewalk bridge level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST2-11/3/2007	Southeast Area (sidewalk bridge level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST4-11/3/2007	Northwest Area (street-level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST5-11/3/2007	Firehouse #10 (roof level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST10-11/3/2007	North Side Sidewalk Bridge	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST100-11/3/2007	Station 10 Field Duplicate	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-11/3/2007	90 Trinity Place (roof level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST12-11/3/2007	110 Greenwich Street (roof level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-11/3/2007	Marriott Hotel, 38th Floor (roof level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-11/3/2007	West Face - South end at corner (scaffolding level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-11/3/2007	South Face - East end at corner (scaffolding level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-11/3/2007	East Face - North end at corner (scaffolding level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-11/3/2007	North Face - West end at corner (scaffolding level)	11/3/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-11/4/2007	Southwest Area (sidewalk bridge level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-11/4/2007	Southeast Area (sidewalk bridge level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST4-11/4/2007	Northwest Area (street-level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST5-11/4/2007	Firehouse #10 (roof level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-11/4/2007	North Side Sidewalk Bridge	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST100-11/4/2007	Station 10 Field Duplicate	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-11/4/2007	110 Greenwich Street (roof level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-11/4/2007	Marriott Hotel, 38th Floor (roof level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-11/4/2007	West Face - South end at corner (scaffolding level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-11/4/2007	South Face - East end at corner (scaffolding level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-11/4/2007	East Face - North end at corner (scaffolding level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-11/4/2007	North Face - West end at corner (scaffolding level)	11/4/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

1. The PM 10 reading at Station 11 (90 Trinity Place [roof level]) on October 4, 2007 was not available on account of instrument malfunction.