

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-11/7/2008	Southwest Area (sidewalk bridge level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST2-11/7/2008	Southeast Area (sidewalk bridge level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	54	No	No	
PM10-ST4-11/7/2008	Northwest Area (street-level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST5-11/7/2008	Firehouse #10 (roof level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST10-11/7/2008	North Side Sidewalk Bridge	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST100-11/7/2008	Station 10 Field Duplicate	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST11-11/7/2008	90 Trinity Place (roof level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-11/7/2008	110 Greenwich Street (roof level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST13-11/7/2008	Marriott Hotel, 38th Floor (roof level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST14-11/7/2008	West Face - South end at corner (scaffolding level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST15-11/7/2008	South Face - East end at corner (scaffolding level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST16-11/7/2008	East Face - North end at corner (scaffolding level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST17-11/7/2008	North Face - West end at corner (scaffolding level)	11/7/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST1-11/8/2008	Southwest Area (sidewalk bridge level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	63	No	No	
PM10-ST2-11/8/2008	Southeast Area (sidewalk bridge level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST4-11/8/2008	Northwest Area (street-level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST5-11/8/2008	Firehouse #10 (roof level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST10-11/8/2008	North Side Sidewalk Bridge	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST100-11/8/2008	Station 10 Field Duplicate	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST11-11/8/2008	90 Trinity Place (roof level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST12-11/8/2008	110 Greenwich Street (roof level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST13-11/8/2008	Marriott Hotel, 38th Floor (roof level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST14-11/8/2008	West Face - South end at corner (scaffolding level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST15-11/8/2008	South Face - East end at corner (scaffolding level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST17-11/8/2008	North Face - West end at corner (scaffolding level)	11/8/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST1-11/9/2008	Southwest Area (sidewalk bridge level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST2-11/9/2008	Southeast Area (sidewalk bridge level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST4-11/9/2008	Northwest Area (street-level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST5-11/9/2008	Firehouse #10 (roof level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST10-11/9/2008	North Side Sidewalk Bridge	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-11/9/2008	Station 10 Field Duplicate	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST11-11/9/2008	90 Trinity Place (roof level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-11/9/2008	110 Greenwich Street (roof level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-11/9/2008	Marriott Hotel, 38th Floor (roof level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-11/9/2008	West Face - South end at corner (scaffolding level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-11/9/2008	South Face - East end at corner (scaffolding level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-11/9/2008	North Face - West end at corner (scaffolding level)	11/9/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

1. PM 10 readings at Station 16 (East Face - North end at corner [scaffolding level]) on November 8 and 9, 2008 were not available on account of instrument malfunction.