

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-11/10/2006	Southwest Area (sidewalk bridge level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-11/10/2006	Southeast Area (sidewalk bridge level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST4-11/10/2006	Northwest Area (street-level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-11/10/2006	North Side Sidewalk Bridge	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST100-11/10/2006	Station 10 Field Duplicate	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-11/10/2006	90 Trinity Place (roof level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-11/10/2006	110 Greenwich Street (roof level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-11/10/2006	Marriott Hotel, 38th Floor (roof level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-11/10/2006	West Face - South end at corner (scaffolding level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST15-11/10/2006	South Face - East end at corner (scaffolding level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-11/10/2006	East Face - North end at corner (scaffolding level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST17-11/10/2006	North Face - West end at corner (scaffolding level)	11/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-11/11/2006	Southwest Area (sidewalk bridge level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST2-11/11/2006	Southeast Area (sidewalk bridge level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST4-11/11/2006	Northwest Area (street-level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST10-11/11/2006	North Side Sidewalk Bridge	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST100-11/11/2006	Station 10 Field Duplicate	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST11-11/11/2006	90 Trinity Place (roof level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST13-11/11/2006	Marriott Hotel, 38th Floor (roof level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST14-11/11/2006	West Face - South end at corner (scaffolding level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST15-11/11/2006	South Face - East end at corner (scaffolding level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST16-11/11/2006	East Face - North end at corner (scaffolding level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST17-11/11/2006	North Face - West end at corner (scaffolding level)	11/11/06	1440	Particulate	Direct Read	Met One E-BAM	57	No	No	
PM10-ST1-11/12/2006	Southwest Area (sidewalk bridge level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-11/12/2006	Southeast Area (sidewalk bridge level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	59	No	No	
PM10-ST5-11/12/2006	Firehouse #10 (roof level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST10-11/12/2006	North Side Sidewalk Bridge	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	58	No	No	
PM10-ST100-11/12/2006	Station 10 Field Duplicate	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	76	No	No	
PM10-ST11-11/12/2006	90 Trinity Place (roof level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	61	No	No	
PM10-ST12-11/12/2006	110 Greenwich Street (roof level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	54	No	No	
PM10-ST13-11/12/2006	Marriott Hotel, 38th Floor (roof level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	56	No	No	
PM10-ST14-11/12/2006	West Face - South end at corner (scaffolding level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST15-11/12/2006	South Face - East end at corner (scaffolding level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST16-11/12/2006	East Face - North end at corner (scaffolding level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST17-11/12/2006	North Face - West end at corner (scaffolding level)	11/12/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	

Note:

1. PM 10 readings at Station 5 (Firehouse #10 [roof level]) on November 10 and 11, 2006 were not available on account of instrument malfunction.
2. PM 10 reading at Station 12 (110 Greenwich Street [roof level]) on November 11, 2006 was not available on account of instrument malfunction.
3. PM 10 reading at Station 4 (Northwest Area [street-level]) on November 12, 2006 was not available on account of instrument malfunction.