

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM10-ST1-11/19/2008	Southwest Area (sidewalk bridge level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-11/19/2008	Southeast Area (sidewalk bridge level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-11/19/2008	Northwest Area (street-level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST5-11/19/2008	Firehouse #10 (roof level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST10-11/19/2008	North Side Sidewalk Bridge	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST100-11/19/2008	Station 10 Field Duplicate	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-11/19/2008	90 Trinity Place (roof level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST12-11/19/2008	110 Greenwich Street (roof level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-11/19/2008	Marriott Hotel, 38th Floor (roof level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-11/19/2008	West Face - South end at corner (scaffolding level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-11/19/2008	South Face - East end at corner (scaffolding level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST16-11/19/2008	East Face - North end at corner (scaffolding level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST17-11/19/2008	North Face - West end at corner (scaffolding level)	11/19/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST2-11/20/2008	Southeast Area (sidewalk bridge level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST4-11/20/2008	Northwest Area (street-level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST5-11/20/2008	Firehouse #10 (roof level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST10-11/20/2008	North Side Sidewalk Bridge	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-11/20/2008	Station 10 Field Duplicate	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST11-11/20/2008	90 Trinity Place (roof level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST12-11/20/2008	110 Greenwich Street (roof level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST13-11/20/2008	Marriott Hotel, 38th Floor (roof level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST14-11/20/2008	West Face - South end at corner (scaffolding level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-11/20/2008	South Face - East end at corner (scaffolding level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST16-11/20/2008	East Face - North end at corner (scaffolding level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST17-11/20/2008	North Face - West end at corner (scaffolding level)	11/20/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	

Note:

1. The PM10 reading at Station 1 (southwest Area [sidewalk bridge level]) on November 20, 2008 was not available on account of intermittent power outages.