TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
		<b>Target Air Quality Leve</b>	ls				150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-12/24/2008	Southwest Area (sidewalk bridge level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST2-12/24/2008	Southeast Area (sidewalk bridge level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	62	No	No	
PM10-ST5-12/24/2008	Firehouse #10 (roof level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-12/24/2008	North Side Sidewalk Bridge	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST100-12/24/2008	Station 10 Field Duplicate	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-12/24/2008	90 Trinity Place (roof level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST12-12/24/2008	110 Greenwich Street (roof level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST13-12/24/2008	Marriott Hotel, 38th Floor (roof level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST14-12/24/2008	West Face - South end at corner (scaffolding level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST15-12/24/2008	South Face - East end at corner (scaffolding level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST17-12/24/2008	North Face - West end at corner (scaffolding level)	12/24/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-12/25/2008	Southwest Area (sidewalk bridge level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-12/25/2008	Southeast Area (sidewalk bridge level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST5-12/25/2008	Firehouse #10 (roof level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST10-12/25/2008	North Side Sidewalk Bridge	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST100-12/25/2008	Station 10 Field Duplicate	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST11-12/25/2008	90 Trinity Place (roof level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST12-12/25/2008	110 Greenwich Street (roof level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-12/25/2008	Marriott Hotel, 38th Floor (roof level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-12/25/2008	West Face - South end at corner (scaffolding level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-12/25/2008	South Face - East end at corner (scaffolding level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST16-12/25/2008	East Face - North end at corner (scaffolding level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST17-12/25/2008	North Face - West end at corner (scaffolding level)	12/25/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	

- The PM10 readings from Station 4 (Northwest Area [street-level]) on December 24 and 25, 2008 were not available on account of power failure.
  The PM10 reading from Station 16 (East Face North end at corner [scaffolding level]) on December 24, 2008 was not available on account of power failure.