

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-2/22/2008	Southwest Area (sidewalk bridge level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST2-2/22/2008	Southeast Area (sidewalk bridge level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST4-2/22/2008	Northwest Area (street-level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST10-2/22/2008	North Side Sidewalk Bridge	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST100-2/22/2008	Station 10 Field Duplicate	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST11-2/22/2008	90 Trinity Place (roof level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST12-2/22/2008	110 Greenwich Street (roof level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST13-2/22/2008	Marriott Hotel, 38th Floor (roof level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST14-2/22/2008	West Face - South end at corner (scaffolding level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM2.5-ST16-2/22/2008	East Face - North end at corner (scaffolding level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST17-2/22/2008	North Face - West end at corner (scaffolding level)	2/22/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST1-2/23/2008	Southwest Area (sidewalk bridge level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST2-2/23/2008	Southeast Area (sidewalk bridge level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST4-2/23/2008	Northwest Area (street-level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST10-2/23/2008	North Side Sidewalk Bridge	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST100-2/23/2008	Station 10 Field Duplicate	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST11-2/23/2008	90 Trinity Place (roof level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST12-2/23/2008	110 Greenwich Street (roof level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST13-2/23/2008	Marriott Hotel, 38th Floor (roof level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST14-2/23/2008	West Face - South end at corner (scaffolding level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST15-2/23/2008	South Face - East end at corner (scaffolding level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST16-2/23/2008	East Face - North end at corner (scaffolding level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST17-2/23/2008	North Face - West end at corner (scaffolding level)	2/23/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST1-2/24/2008	Southwest Area (sidewalk bridge level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-2/24/2008	Southeast Area (sidewalk bridge level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST4-2/24/2008	Northwest Area (street-level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST10-2/24/2008	North Side Sidewalk Bridge	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST100-2/24/2008	Station 10 Field Duplicate	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST11-2/24/2008	90 Trinity Place (roof level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST12-2/24/2008	110 Greenwich Street (roof level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-2/24/2008	Marriott Hotel, 38th Floor (roof level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST14-2/24/2008	West Face - South end at corner (scaffolding level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST15-2/24/2008	South Face - East end at corner (scaffolding level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST16-2/24/2008	East Face - North end at corner (scaffolding level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST17-2/24/2008	North Face - West end at corner (scaffolding level)	2/24/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	

Note:

1. The PM 2.5 readings at Station 5 (Firehouse #10 [roof level]) on February 22 through 24, 2008 were not available on account of instrument malfunction.
2. The PM 2.5 reading at (Station 11 South Face - East end at corner [scaffolding level]) on February 22, 2008 was not available on account of instrument malfunction.