

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM2.5-ST1-4/17/2006	Southwest Area (sidewalk bridge level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST2-4/17/2006	Southeast Area (sidewalk bridge level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST4-4/17/2006	Northwest Area (street-level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST5-4/17/2006	Firehouse #10 (roof level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST10-4/17/2006	North Side Sidewalk Bridge	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST100-4/17/2006	Station 10 Field Duplicate	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST11-4/17/2006	90 Trinity Place (roof level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST12-4/17/2006	110 Greenwich Street (roof level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST13-4/17/2006	Marriott Hotel, 38th Floor (roof level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST14-4/17/2006	West Face - South end at corner (scaffolding level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST15-4/17/2006	South Face - East end at corner (scaffolding level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST16-4/17/2006	East Face - North end at corner (scaffolding level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST17-4/17/2006	North Face - West end at corner (scaffolding level)	4/17/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST1-4/18/2006	Southwest Area (sidewalk bridge level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-4/18/2006	Southeast Area (sidewalk bridge level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST4-4/18/2006	Northwest Area (street-level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST5-4/18/2006	Firehouse #10 (roof level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST10-4/18/2006	North Side Sidewalk Bridge	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST100-4/18/2006	Station 10 Field Duplicate	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	3	No	No	
PM2.5-ST11-4/18/2006	90 Trinity Place (roof level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	2	No	No	
PM2.5-ST12-4/18/2006	110 Greenwich Street (roof level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST13-4/18/2006	Marriott Hotel, 38th Floor (roof level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST14-4/18/2006	West Face - South end at corner (scaffolding level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST15-4/18/2006	South Face - East end at corner (scaffolding level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST16-4/18/2006	East Face - North end at corner (scaffolding level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST17-4/18/2006	North Face - West end at corner (scaffolding level)	4/18/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	