

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-8/16/2006	Southwest Area (sidewalk bridge level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST2-8/16/2006	Southeast Area (sidewalk bridge level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST4-8/16/2006	Northwest Area (street-level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST5-8/16/2006	Firehouse #10 (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST6-8/16/2006	Southwest Area (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST7-8/16/2006	Southeast Area (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST8-8/16/2006	Northeast Area (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST9-8/16/2006	Northwest Area (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-8/16/2006	North Side Sidewalk Bridge	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST100-8/16/2006	Station 10 Field Duplicate	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST11-8/16/2006	90 Trinity Place (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST12-8/16/2006	110 Greenwich Street (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST13-8/16/2006	Marriott Hotel, 38th Floor (roof level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST14-8/16/2006	West Face - South end at corner (scaffolding level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST15-8/16/2006	South Face - East end at corner (scaffolding level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST16-8/16/2006	East Face - North end at corner (scaffolding level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST17-8/16/2006	North Face - West end at corner (scaffolding level)	8/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST1-8/17/2006	Southwest Area (sidewalk bridge level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST2-8/17/2006	Southeast Area (sidewalk bridge level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST4-8/17/2006	Northwest Area (street-level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST5-8/17/2006	Firehouse #10 (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST6-8/17/2006	Southwest Area (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST7-8/17/2006	Southeast Area (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST8-8/17/2006	Northeast Area (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST10-8/17/2006	North Side Sidewalk Bridge	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST100-8/17/2006	Station 10 Field Duplicate	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-8/17/2006	90 Trinity Place (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST12-8/17/2006	110 Greenwich Street (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST13-8/17/2006	Marriott Hotel, 38th Floor (roof level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST14-8/17/2006	West Face - South end at corner (scaffolding level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST15-8/17/2006	South Face - East end at corner (scaffolding level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST16-8/17/2006	East Face - North end at corner (scaffolding level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST17-8/17/2006	North Face - West end at corner (scaffolding level)	8/17/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

1. The PM 2.5 reading at Station 9 (Northwest Area [roof level]) on August 17, 2006 was not available on account of instrument malfunction.