

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
PM2.5-ST1-11/28/2007	Southwest Area (sidewalk bridge level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST2-11/28/2007	Southeast Area (sidewalk bridge level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST4-11/28/2007	Northwest Area (street-level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST5-11/28/2007	Firehouse #10 (roof level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST10-11/28/2007	North Side Sidewalk Bridge	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST100-11/28/2007	Station 10 Field Duplicate	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST11-11/28/2007	90 Trinity Place (roof level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST12-11/28/2007	110 Greenwich Street (roof level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST13-11/28/2007	Marriott Hotel, 38th Floor (roof level)	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST14-11/28/2007	West Face - South end at corner	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST15-11/28/2007	South Face - East end at corner	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST16-11/28/2007	East Face - North end at corner	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST17-11/28/2007	North Face - West end at corner	11/28/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST1-11/29/2007	Southwest Area (sidewalk bridge level)	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST2-11/29/2007	Southeast Area (sidewalk bridge level)	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST4-11/29/2007	Northwest Area (street-level)	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-11/29/2007	North Side Sidewalk Bridge	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST100-11/29/2007	Station 10 Field Duplicate	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST11-11/29/2007	90 Trinity Place (roof level)	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST12-11/29/2007	110 Greenwich Street (roof level)	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST13-11/29/2007	Marriott Hotel, 38th Floor (roof level)	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST14-11/29/2007	West Face - South end at corner	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST15-11/29/2007	South Face - East end at corner	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST16-11/29/2007	East Face - North end at corner	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST17-11/29/2007	North Face - West end at corner	11/29/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	

Note:

1. The PM 2.5 reading at Station 5 (Firehouse #10 [roof level]) on November 29, 2007 was not available on account of power failure.