

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM2.5-ST1-12/26/2008	Southwest Area (sidewalk bridge level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST2-12/26/2008	Southeast Area (sidewalk bridge level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST4-12/26/2008	Northwest Area (street-level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST5-12/26/2008	Firehouse #10 (roof level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST10-12/26/2008	North Side Sidewalk Bridge	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST100-12/26/2008	Station 10 Field Duplicate	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST11-12/26/2008	90 Trinity Place (roof level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST12-12/26/2008	110 Greenwich Street (roof level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST13-12/26/2008	Marriott Hotel, 38th Floor (roof level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST14-12/26/2008	West Face - South end at corner (scaffolding level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST15-12/26/2008	South Face - East end at corner (scaffolding level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST16-12/26/2008	East Face - North end at corner (scaffolding level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST17-12/26/2008	North Face - West end at corner (scaffolding level)	12/26/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST1-12/27/2008	Southwest Area (sidewalk bridge level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST2-12/27/2008	Southeast Area (sidewalk bridge level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM2.5-ST4-12/27/2008	Northwest Area (street-level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST5-12/27/2008	Firehouse #10 (roof level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST10-12/27/2008	North Side Sidewalk Bridge	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST100-12/27/2008	Station 10 Field Duplicate	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST11-12/27/2008	90 Trinity Place (roof level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST12-12/27/2008	110 Greenwich Street (roof level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST13-12/27/2008	Marriott Hotel, 38th Floor (roof level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST14-12/27/2008	West Face - South end at corner (scaffolding level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST15-12/27/2008	South Face - East end at corner (scaffolding level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST16-12/27/2008	East Face - North end at corner (scaffolding level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST17-12/27/2008	North Face - West end at corner (scaffolding level)	12/27/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST1-12/28/2008	Southwest Area (sidewalk bridge level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-12/28/2008	Southeast Area (sidewalk bridge level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST4-12/28/2008	Northwest Area (street-level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST5-12/28/2008	Firehouse #10 (roof level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-12/28/2008	North Side Sidewalk Bridge	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST11-12/28/2008	90 Trinity Place (roof level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST12-12/28/2008	110 Greenwich Street (roof level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST13-12/28/2008	Marriott Hotel, 38th Floor (roof level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST14-12/28/2008	West Face - South end at corner (scaffolding level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST16-12/28/2008	East Face - North end at corner (scaffolding level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST17-12/28/2008	North Face - West end at corner (scaffolding level)	12/28/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	

Note:

1. The PM2.5 reading from Station 100 (Station 10 Field Duplicate) on December 28, 2008 was not available on account of instrument malfunction.
2. The PM2.5 reading from Station 15 (South Face - East end at corner [scaffolding level]) on December 28, 2008 was not available on account of instrument malfunction.