

**SUMMARY OF AIR SAMPLING RESULTS AT
130 CEDAR STREET**

No.	Location	RESULTS							
		Round 1		Round 2		Round 3		Round 4	
		PCM f/cc	TEM s/mm ²	PCM f/cc	TEM s/mm ²	PCM f/cc	TEM s/mm ²	PCM f/cc	TEM s/mm ²
1	130 Cedar St: 8 - Roof - North Façade	0.002	NAD (<19.00)	0.002	NAD (<11.00)	<0.002	NAD (<15.00)	<0.002	NAD (<19.00)
2	130 Cedar St: 7 - Roof - East Façade	<0.002	NAD (<19.00)	0.002	NAD (<11.00)	<0.002	NAD (<15.00)	<0.002	NAD (<19.00)
3	130 Cedar St - 6th Floor Scaffolding	<0.002	NAD (<19.00)	0.002	NAD (<11.00)	<0.002	NAD (<15.00)	<0.002	NAD (<15.00)
4	130 Cedar St - Washington St - 6th Floor Scaffolding	<0.001	NAD (<19.00)	0.002	NAD (<11.00)	<0.002	NAD (<15.00)	<0.002	NAD (<19.00)
5	130 Cedar St - Albany St - 6th Floor Scaffolding	<0.002	NAD (<19.00)	0.002	NAD (<11.00)	<0.002	NAD (<15.00)	<0.002	NAD (<15.00)
6	130 Cedar Street: 6- Cedar Street 6th Floor Scaffolding								
7	130 Cedar Street: 3- 90 West Courtyard Level								

Round 1 - 10:15pm - 1:15 am (8/18) (08/18/07)
 Round 2 - 1:15am - 9:15am (8/19) (08/19/07)
 Round 3 - 9:15am - 5:00pm (8/19) (08/19/07)
 Round 4 - 5:15pm - 8:00am (8/19) (08/19/07) to (08/20/07)
 Round 5 - 8:00 am - 1:00pm (8/20)
 Round 6 - 8:00 am - 1:00pm (8/20)
 Round 7 - 8:00 am - 1:00pm (8/20)
 Round 8 - 8:00 am - 1:00pm (8/21)

NAD - No Asbestos Detected
 TEM - Transmission Electron Microscopy
 PCM - Phase Contrast Microscopy

SUMMARY OF THE 20th FLOOR AIR SAMPLING RESULTS
130 LIBERTY STREET, NEW YORK, NY

No.	Location	RESULTS		
		Asbestos		Metals
		PCM f/cc	TEM s/mm ²	NIOSH 7300 ug/m ³
1	IWA/ NORTH SIDE OF 20TH FL IN THE MIDDLE	<0.002	NAD (<15.00)	Below clearance level
2	IWA/ NORTH EAST SIDE OF 20TH FLOOR	<0.002	NAD (<15.00)	Below clearance level
3	IWA/ EAST SIDE OF 20TH FL, IN THE MIDDLE	<0.002	NAD (<15.00)	Below clearance level
4	IWA/ 20TH FL NEXT TO STAIRWELL 1 ON SOUTH SIDE	<0.002	NAD (<15.00)	Below clearance level
5	IWA/ SOUTH WEST SIDE OF 20TH FL	<0.002	NAD (<15.00)	Below clearance level
6	IWA/ WEST SIDE OF 20TH FL, IN THE MIDDLE	<0.002	NAD (<15.00)	Below clearance level
7	IWA/ NORTH WEST SIDE OF 20TH FL	<0.002	NAD (<15.00)	Below clearance level
8	Field Blank	---	---	---
9	Field Blank	---	---	---

7

7

7

NAD - No Asbestos Detected
TEM - Transmission Electron Microscopy
PCM - Phase Contrast Microscopy