TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target	Exceeds EPA	
	0.25	Air Quality	Site Specific Cor	omments								
	25	Levels	Trigger Levels									
Dioxins/Furans-ST2-3/7/06	P6425_3908_003	Southeast Area (sidewalk bridge level)	3/7/06	336	Dioxin	TO-9A	AP	3/9/06	0.0398	No	No	
Dioxins/Furans-ST10-3/7/06	P6425_3908_006	North Side Sidewalk Bridge	3/7/06	323	Dioxin	TO-9A	AP	3/9/06	0.0256	No	No	
Dioxins/Furans-ST100-3/7/06	P6425_3928_013	Station 10 Field Duplicate	3/7/06	360	Dioxin	TO-9A	AP	3/9/06	0.0309	No	No	