

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									0.25			
									25			
Dioxins/Furans-ST1-3/15/06	P6453_3933_002CU	Southwest Area (sidewalk bridge level)	3/15/06	362	Dioxin	TO-9A	AP	3/17/06	0.0391	No	No	
Dioxins/Furans-ST2-3/15/06	P6453_3933_003	Southeast Area (sidewalk bridge level)	3/15/06	352	Dioxin	TO-9A	AP	3/17/06	0.0216	No	No	
Dioxins/Furans-ST4-3/15/06	P6453_3933_004CU	Northwest Area (street-level)	3/15/06	317	Dioxin	TO-9A	AP	3/17/06	0.0249	No	No	
Dioxins/Furans-ST5-3/15/06	P6453_3933_005	Firehouse #10 (roof level)	3/15/06	332	Dioxin	TO-9A	AP	3/17/06	0.0243	No	No	
Dioxins/Furans-ST10-3/15/06	P6453_3933_006	North Side Sidewalk Bridge	3/15/06	326	Dioxin	TO-9A	AP	3/17/06	0.0261	No	No	
Dioxins/Furans-ST100-3/15/06	P6453_3933_014	Station 10 Field Duplicate	3/15/06	297	Dioxin	TO-9A	AP	3/17/06	0.0545	No	No	
Dioxins/Furans-ST11-3/15/06	P6453_3933_007	90 Trinity Place (roof level)	3/15/06	330	Dioxin	TO-9A	AP	3/17/06	0.0219	No	No	
Dioxins/Furans-ST12-3/15/06	P6453_3933_008	110 Greenwich Street (roof level)	3/15/06	326	Dioxin	TO-9A	AP	3/17/06	0.0325	No	No	
Dioxins/Furans-ST13-3/15/06	P6453_3933_009	Marriott Hotel, 38th Floor (roof level)	3/15/06	386	Dioxin	TO-9A	AP	3/17/06	0.0298	No	No	
Dioxins/Furans-ST14-3/15/06	P6453_3933_010	West Face - South end at corner (scaffolding level)	3/15/06	343	Dioxin	TO-9A	AP	3/17/06	0.0303	No	No	
Dioxins/Furans-ST15-3/15/06	P6453_3933_011	South Face - East end at corner (scaffolding level)	3/15/06	356	Dioxin	TO-9A	AP	3/17/06	0.0337	No	No	
Dioxins/Furans-ST16-3/15/06	P6453_3933_012	East Face - North end at corner (scaffolding level)	3/15/06	351	Dioxin	TO-9A	AP	3/17/06	0.0354	No	No	
Dioxins/Furans-ST17-3/15/06	P6453_3933_013	North Face - West end at corner (scaffolding level)	3/15/06	358	Dioxin	TO-9A	AP	3/17/06	0.034	No	No	