

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									0.25			
									25			
Dioxins/Furans-ST1-3/16/06	P6457_3935_002	Southwest Area (sidewalk bridge level)	3/16/06	328	Dioxin	TO-9A	AP	3/18/06	0.0502	No	No	
Dioxins/Furans-ST2-3/16/06	P6457_3935_003	Southeast Area (sidewalk bridge level)	3/16/06	304	Dioxin	TO-9A	AP	3/18/06	0.0344	No	No	
Dioxins/Furans-ST4-3/16/06	P6457_3935_004	Northwest Area (street-level)	3/16/06	315	Dioxin	TO-9A	AP	3/18/06	0.0307	No	No	
Dioxins/Furans-ST5-3/16/06	P6457_3935_005	Firehouse #10 (roof level)	3/16/06	345	Dioxin	TO-9A	AP	3/18/06	0.023	No	No	
Dioxins/Furans-ST10-3/16/06	P6457_3935_006	North Side Sidewalk Bridge	3/16/06	318	Dioxin	TO-9A	AP	3/18/06	0.0292	No	No	
Dioxins/Furans-ST100-3/16/06	P6457_3935_014	Station 10 Field Duplicate	3/16/06	315	Dioxin	TO-9A	AP	3/18/06	0.0575	No	No	
Dioxins/Furans-ST11-3/16/06	P6457_3935_007	90 Trinity Place (roof level)	3/16/06	330	Dioxin	TO-9A	AP	3/18/06	0.0384	No	No	
Dioxins/Furans-ST12-3/16/06	P6457_3935_008	110 Greenwich Street (roof level)	3/16/06	325	Dioxin	TO-9A	AP	3/18/06	0.053	No	No	
Dioxins/Furans-ST13-3/16/06	P6457_3935_009	Marriott Hotel, 38th Floor (roof level)	3/16/06	382	Dioxin	TO-9A	AP	3/18/06	0.026	No	No	
Dioxins/Furans-ST14-3/16/06	P6457_3935_010	West Face - South end at corner (scaffolding level)	3/16/06	347	Dioxin	TO-9A	AP	3/18/06	0.0515	No	No	
Dioxins/Furans-ST15-3/16/06	P6457_3935_011	South Face - East end at corner (scaffolding level)	3/16/06	329	Dioxin	TO-9A	AP	3/18/06	0.0401	No	No	
Dioxins/Furans-ST16-3/16/06	P6457_3935_012	East Face - North end at corner (scaffolding level)	3/16/06	343	Dioxin	TO-9A	AP	3/18/06	0.0535	No	No	
Dioxins/Furans-ST17-3/16/06	P6457_3935_013	North Face - West end at corner (scaffolding level)	3/16/06	331	Dioxin	TO-9A	AP	3/18/06	0.0411	No	No	