

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									0.25			
EPA Site Specific Trigger Levels									25			
Dioxins/Furans-ST10-07/05/07	P8056_5048_006	North Side Sidewalk Bridge	7/5/07	352	Dioxin	TO-9A	AP	7/7/07	0.0414	No	No	
Dioxins/Furans-ST100-07/05/07	P8056_5048_014	Station 10 Field Duplicate	7/5/07	338	Dioxin	TO-9A	AP	7/7/07	0.0485	No	No	
Dioxins/Furans-ST11-07/05/07	P8056_5048_007	90 Trinity Place (roof level)	7/5/07	352	Dioxin	TO-9A	AP	7/7/07	0.0285	No	No	