

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>0.25</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>25</b>			
Dioxins/Furans-ST10-10/17/07	P8514_5321_006RJ	North Side Sidewalk Bridge	10/17/07	344	Dioxin	TO-9A	AP	10/19/07	0.0345	No	No	
Dioxins/Furans-ST100-10/17/07	P8514_5321_014RJ	Station 10 Field Duplicate	10/17/07	331	Dioxin	TO-9A	AP	10/19/07	0.035	No	No	
Dioxins/Furans-ST11-10/17/07	P8514_5321_007RJ	90 Trinity Place (roof level)	10/17/07	353	Dioxin	TO-9A	AP	10/19/07	0.0306	No	No	