

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Total PCBs Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									0.12			
EPA Site Specific Trigger Levels									12			
PCBS-ST4-3/12/09	AM02325	Northwest Area (street-level)	3/12/09	6.86	PCBs	EPA Method TO-10A/EPA 8082	Northeast	3/14/09	< 0.102	No	No	
PCBS-ST10-3/12/09	AM02327	North Side Sidewalk Bridge	3/12/09	6.58	PCBs	EPA Method TO-10A/EPA 8082	Northeast	3/14/09	< 0.106	No	No	
PCBS-ST100-3/12/09	AM02335RR1	Station 10 Field Duplicate	3/12/09	6.71	PCBs	EPA Method TO-10A/EPA 8082	Northeast	3/14/09	< 0.104	No	No	

Note:

- The PCBs samples at Station 4 (Northwest Area [street-level]), Station 10 (North Side Sidewalk Bridge) and Station 100 (Station 10 Field Duplicate) on March 12, 2009 had a slightly reduced volume due to a 88 minute power outage.