

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
ASBESTOS-ST1-12/20/08	030844409-0001	Southwest Area (sidewalk bridge level)	12/20/08	1	3.010	Asbestos	PCME	EMSL	12/22/08	< 0.00082	No	No	
ASBESTOS-ST2-12/20/08	030844409-0002	Southeast Area (sidewalk bridge level)	12/20/08	1	2.980	Asbestos	PCME	EMSL	12/22/08	< 0.00083	No	No	
ASBESTOS-ST4-12/20/08	030844409-0003	Northwest Area (street-level)	12/20/08	1	3.060	Asbestos	PCME	EMSL	12/22/08	< 0.00081	No	No	
ASBESTOS-ST5-12/20/08	030844409-0004	Firehouse #10 (roof level)	12/20/08	1	3.000	Asbestos	PCME	EMSL	12/22/08	< 0.00082	No	No	
ASBESTOS-ST10-12/20/08	030844409-0005	North Side Sidewalk Bridge	12/20/08	1	3.080	Asbestos	PCME	EMSL	12/22/08	< 0.00080	No	No	
ASBESTOS-ST11-12/20/08	030844409-0006	90 Trinity Place (roof level)	12/20/08	1	3.020	Asbestos	PCME	EMSL	12/22/08	< 0.00082	No	No	
ASBESTOS-ST12-12/20/08	030844409-0007	110 Greenwich Street (roof level)	12/20/08	1	3.030	Asbestos	PCME	EMSL	12/22/08	< 0.00081	No	No	
ASBESTOS-ST13-12/20/08	030844409-0008	Marriott Hotel, 38th Floor (roof level)	12/20/08	1	2.990	Asbestos	PCME	EMSL	12/22/08	< 0.00083	No	No	
ASBESTOS-ST15-12/20/08	030844535-0001	South Face - East end at corner (scaffolding level)	12/20/08	1	9.580	Asbestos	PCME	EMSL	12/23/08	< 0.00026	No	No	Note 2
ASBESTOS-ST16-12/20/08	030844535-0002	East Face - North end at corner (scaffolding level)	12/20/08	1	9.650	Asbestos	PCME	EMSL	12/23/08	< 0.00026	No	No	Note 2
ASBESTOS-ST17-12/20/08	030844535-0003	North Face - West end at corner (scaffolding level)	12/20/08	1	9.620	Asbestos	PCME	EMSL	12/23/08	< 0.00026	No	No	Note 2

- Note:
- Asbestos samples from Station 14 (West Face - South end at corner [scaffolding level]) on December 20, 2008 was not available for analysis on account of pump failure.
  - Asbestos sample volumes at Station 15 [South Face - East end at corner [scaffolding level]], Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on December 20, 2008 represent 3 consecutive 24-hour periods as samples could not be retrieved on December 21 and 22, 2008 due to hazardous conditions posed by ice and snow on the scaffolding.