TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-7/6/2010	Southwest Area (sidewalk bridge level)	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST2-7/6/2010	Southeast Area (sidewalk bridge level)	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST4-7/6/2010	Northwest Area (street-level)	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST5-7/6/2010	Firehouse #10 (roof level)	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-7/6/2010	90 Trinity Place (roof level)	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST12-7/6/2010	110 Greenwich Street (roof level)	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST20-7/6/2010	Northeast Area, Sidewalk Bridge	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST200-7/6/2010	Station 20 Field Duplicate	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST21-7/6/2010	Marriott Hotel, 4th Floor	7/6/10	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	