TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-9/5/2007	Southwest Area (sidewalk bridge level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST2-9/5/2007	Southeast Area (sidewalk bridge level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST4-9/5/2007	Northwest Area (street-level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST5-9/5/2007	Firehouse #10 (roof level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST10-9/5/2007	North Side Sidewalk Bridge	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST100-9/5/2007	Station 10 Field Duplicate	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST11-9/5/2007	90 Trinity Place (roof level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST12-9/5/2007	110 Greenwich Street (roof level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST13-9/5/2007	Marriott Hotel, 38th Floor (roof level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-9/5/2007	West Face - South end at corner (scaffolding level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST15-9/5/2007	South Face - East end at corner (scaffolding level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST16-9/5/2007	East Face - North end at corner (scaffolding level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST17-9/5/2007	North Face - West end at corner (scaffolding level)	9/5/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	