TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-9/8/2009	Southwest Area (sidewalk bridge level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST2-9/8/2009	Southeast Area (sidewalk bridge level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST4-9/8/2009	Northwest Area (street-level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST10-9/8/2009	North Side Sidewalk Bridge	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST100-9/8/2009	Station 10 Field Duplicate	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-9/8/2009	90 Trinity Place (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST12-9/8/2009	110 Greenwich Street (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST13-9/8/2009	Marriott Hotel, 38th Floor (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	

Note:

1. The PM10 reading from Station 5 (Firehouse #10 [roof level]) on September 8, 2009 was not available on account of instrument malfunction.