

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-5/26/2009	Southwest Area (sidewalk bridge level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST2-5/26/2009	Southeast Area (sidewalk bridge level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST4-5/26/2009	Northwest Area (street-level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST5-5/26/2009	Firehouse #10 (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST10-5/26/2009	North Side Sidewalk Bridge	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST100-5/26/2009	Station 10 Field Duplicate	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST11-5/26/2009	90 Trinity Place (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST12-5/26/2009	110 Greenwich Street (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST13-5/26/2009	Marriott Hotel, 38th Floor (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST14-5/26/2009	West Face - South end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST15-5/26/2009	South Face - East end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST16-5/26/2009	East Face - North end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST17-5/26/2009	North Face - West end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	