

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									10			
SILICA-ST1-1/10/08	040800736-0001	Southwest Area (sidewalk bridge level)	1/10/08	3.46	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST2-1/10/08	040800736-0002	Southeast Area (sidewalk bridge level)	1/10/08	3.61	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST4-1/10/08	040800736-0003	Northwest Area (street-level)	1/10/08	3.7	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST5-1/10/08	040800736-0004	Firehouse #10 (roof level)	1/10/08	3.56	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST10-1/10/08	040800736-0005	North Side Sidewalk Bridge	1/10/08	3.68	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST11-1/10/08	040800736-0006	90 Trinity Place (roof level)	1/10/08	3.61	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST12-1/10/08	040800736-0007	110 Greenwich Street (roof level)	1/10/08	3.63	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST13-1/10/08	040800736-0008	Marriott Hotel, 38th Floor (roof level)	1/10/08	3.57	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST14(15th) -1/10/08	040800736-0009	West Face - South end at corner (scaffolding level: 15th floor)	1/10/08	3.65	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST15(15th) -1/10/08	040800736-0010	South Face - East end at corner (scaffolding level: 15th floor)	1/10/08	3.66	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST16(15th) -1/10/08	040800736-0011	East Face - North end at corner (scaffolding level: 15th floor)	1/10/08	3.61	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	
SILICA-ST17(15th) -1/10/08	040800736-0012	North Face - West end at corner (scaffolding level: 15th floor)	1/10/08	3.66	Silica	NIOSH 7500 XRD	EMSL	1/11/08	< 1	No	No	