

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-1/12/11	041100920-0001	Southwest Area (sidewalk bridge level)	1/12/11	3.42	Silica	NIOSH 7500 XRD	EMSL	1/14/11	< 1	No	No	
SILICA-ST2-1/12/11	041100920-0002	Southeast Area (sidewalk bridge level)	1/12/11	3.67	Silica	NIOSH 7500 XRD	EMSL	1/14/11	< 1	No	No	
SILICA-ST5-1/12/11	041100920-0003	Firehouse #10 (roof level)	1/12/11	3.62	Silica	NIOSH 7500 XRD	EMSL	1/14/11	< 1	No	No	
SILICA-ST23-1/12/11	041100920-0004	Northwest Area (sidewalk bridge level)	1/12/11	3.56	Silica	NIOSH 7500 XRD	EMSL	1/14/11	< 1	No	No	