

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-2/5/06	040602324-0001	Southwest Area (sidewalk bridge level)	2/5/06	3.67	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST2-2/5/06	040602324-0002	Southeast Area (sidewalk bridge level)	2/5/06	3.62	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST4-2/5/06	040602324-0003	Northwest Area (street-level)	2/5/06	3.68	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST5-2/5/06	040602324-0004	Firehouse #10 (roof level)	2/5/06	3.68	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST10-2/5/06	040602324-0005	North Side Sidewalk Bridge	2/5/06	3.73	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST11-2/5/06	040602324-0006	90 Trinity Place (roof level)	2/5/06	3.48	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST12-2/5/06	040602324-0007	110 Greenwich Street (roof level)	2/5/06	3.48	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST13-2/5/06	040602324-0008	Marriott Hotel, 38th Floor (roof level)	2/5/06	3.52	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST14-2/5/06	040602324-0009	West Face - South end at corner (scaffolding level)	2/5/06	3.9	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST15-2/5/06	040602324-0010	South Face - East end at corner (scaffolding level)	2/5/06	3.88	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST16-2/5/06	040602324-0011	East Face - North end at corner (scaffolding level)	2/5/06	3.87	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST17-2/5/06	040602324-0012	North Face - West end at corner (scaffolding level)	2/5/06	3.89	Silica	NIOSH 7500 XRD	EMSL	2/6/06	< 1	No	No	
SILICA-ST1-2/6/06	040602398-0001	Southwest Area (sidewalk bridge level)	2/6/06	3.36	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST2-2/6/06	040602398-0002	Southeast Area (sidewalk bridge level)	2/6/06	3.37	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST4-2/6/06	040602398-0003	Northwest Area (street-level)	2/6/06	3.36	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST5-2/6/06	040602398-0004	Firehouse #10 (roof level)	2/6/06	3.56	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST10-2/6/06	040602398-0005	North Side Sidewalk Bridge	2/6/06	3.33	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 2	No	No	
SILICA-ST11-2/6/06	040602398-0006	90 Trinity Place (roof level)	2/6/06	3.6	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST12-2/6/06	040602398-0007	110 Greenwich Street (roof level)	2/6/06	3.72	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST13-2/6/06	040602398-0008	Marriott Hotel, 38th Floor (roof level)	2/6/06	3.43	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST14-2/6/06	040602398-0009	West Face - South end at corner (scaffolding level)	2/6/06	3.6	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST15-2/6/06	040602398-0010	South Face - East end at corner (scaffolding level)	2/6/06	3.61	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST16-2/6/06	040602398-0011	East Face - North end at corner (scaffolding level)	2/6/06	3.61	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	
SILICA-ST17-2/6/06	040602398-0012	North Face - West end at corner (scaffolding level)	2/6/06	3.6	Silica	NIOSH 7500 XRD	EMSL	2/7/06	< 1	No	No	