

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-2/10/06	040602858-0001	Southwest Area (sidewalk bridge level)	2/10/06	3.54	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST2-2/10/06	040602858-0002	Southeast Area (sidewalk bridge level)	2/10/06	3.53	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST4-2/10/06	040602858-0003	Northwest Area (street-level)	2/10/06	3.46	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST5-2/10/06	040602858-0004	Firehouse #10 (roof level)	2/10/06	3.55	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST10-2/10/06	040602858-0005	North Side Sidewalk Bridge	2/10/06	3.45	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST11-2/10/06	040602858-0006	90 Trinity Place (roof level)	2/10/06	3.62	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST12-2/10/06	040602858-0007	110 Greenwich Street (roof level)	2/10/06	3.52	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST13-2/10/06	040602858-0008	Marriott Hotel, 38th Floor (roof level)	2/10/06	3.51	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST14-2/10/06	040602858-0009	West Face - South end at corner (scaffolding level)	2/10/06	3.37	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST15-2/10/06	040602858-0010	South Face - East end at corner (scaffolding level)	2/10/06	3.37	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST16-2/10/06	040602858-0011	East Face - North end at corner (scaffolding level)	2/10/06	3.42	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	
SILICA-ST17-2/10/06	040602858-0012	North Face - West end at corner (scaffolding level)	2/10/06	3.41	Silica	NIOSH 7500 XRD	EMSL	2/13/06	< 1	No	No	