

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-2/16/11	041103637-0001	Southwest Area (sidewalk bridge level)	2/16/11	3.6	Silica	NIOSH 7500 XRD	EMSL	2/18/11	< 1	No	No	
SILICA-ST2-2/16/11	041103637-0002	Southeast Area (sidewalk bridge level)	2/16/11	3.75	Silica	NIOSH 7500 XRD	EMSL	2/18/11	< 1	No	No	
SILICA-ST5-2/16/11	041103637-0003	Firehouse #10 (roof level)	2/16/11	3.72	Silica	NIOSH 7500 XRD	EMSL	2/18/11	< 1	No	No	
SILICA-ST23-2/16/11	041103637-0004	Northwest Area (sidewalk bridge level)	2/16/11	3.85	Silica	NIOSH 7500 XRD	EMSL	2/18/11	< 1	No	No	
SILICA-ST26-2/16/11	041103637-0005	Northwest Area (Ground level)	2/16/11	3.73	Silica	NIOSH 7500 XRD	EMSL	2/18/11	< 1	No	No	