

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST5-2/24/11	041104341-0001	Firehouse #10 (roof level)	2/24/11	3.63	Silica	NIOSH 7500 XRD	EMSL	2/28/11	< 1	No	No	
SILICA-ST24-2/24/11	041104341-0002	Southwest Area (Ground level)	2/24/11	3.65	Silica	NIOSH 7500 XRD	EMSL	2/28/11	< 1	No	No	
SILICA-ST25-2/24/11	041104341-0003	Southeast Area (Ground level)	2/24/11	3.69	Silica	NIOSH 7500 XRD	EMSL	2/28/11	< 1	No	No	
SILICA-ST26-2/24/11	041104341-0004	Northwest Area (Ground level)	2/24/11	3.52	Silica	NIOSH 7500 XRD	EMSL	2/28/11	4	No	No	
SILICA-ST5-2/25/11	041104342-0001	Firehouse #10 (roof level)	2/25/11	3.63	Silica	NIOSH 7500 XRD	EMSL	2/28/11	< 1	No	No	
SILICA-ST26-2/25/11	041104342-0004	Northwest Area (Ground level)	2/25/11	3.69	Silica	NIOSH 7500 XRD	EMSL	2/28/11	< 1	No	No	

Note:

1. Station 24 (Southwest Area [Ground level]), Station 25 (Southeast Area [Ground level]) and Station 2500 (Station 25 Field Duplicate) were removed from service on February 25, 2011. This was in accordance with Amendment #18 to the September 2005 Ambient Air Monitoring Plan.