

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-3/4/10	041004659-0001	Southwest Area (sidewalk bridge level)	3/4/10	3.74	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST2-3/4/10	041004659-0002	Southeast Area (sidewalk bridge level)	3/4/10	3.66	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST4-3/4/10	041004659-0003	Northwest Area (street-level)	3/4/10	3.56	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST5-3/4/10	041004659-0004	Firehouse #10 (roof level)	3/4/10	3.73	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST11-3/4/10	041004659-0006	90 Trinity Place (roof level)	3/4/10	3.59	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST12-3/4/10	041004659-0007	110 Greenwich Street (roof level)	3/4/10	3.49	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST13-3/4/10	041004659-0008	Marriott Hotel, 38th Floor (roof level)	3/4/10	3.61	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST20-3/4/10	041004659-0005	Northeast Area, Sidewalk Bridge	3/4/10	3.61	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	
SILICA-ST200-3/4/10	041004659-0009	Station 20 Field Duplicate	3/4/10	3.69	Silica	NIOSH 7500 XRD	EMSL	3/9/10	< 1	No	No	