

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-3/10/08	040805730-0001	Southwest Area (sidewalk bridge level)	3/10/08	3.41	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST2-3/10/08	040805730-0002	Southeast Area (sidewalk bridge level)	3/10/08	3.49	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST4-3/10/08	040805730-0003	Northwest Area (street-level)	3/10/08	3.57	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST5-3/10/08	040805730-0004	Firehouse #10 (roof level)	3/10/08	3.60	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST10-3/10/08	040805730-0005	North Side Sidewalk Bridge	3/10/08	3.41	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST11-3/10/08	040805730-0006	90 Trinity Place (roof level)	3/10/08	3.60	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST12-3/10/08	040805730-0007	110 Greenwich Street (roof level)	3/10/08	3.62	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST13-3/10/08	040805730-0008	Marriott Hotel, 38th Floor (roof level)	3/10/08	3.63	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST15(15th) -3/10/08	040805730-0009	South Face - East end at corner (scaffolding level: 15th floor)	3/10/08	3.52	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST16(15th) -3/10/08	040805730-0010	East Face - North end at corner (scaffolding level: 15th floor)	3/10/08	3.55	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST17(15th) -3/10/08	040805730-0011	North Face - West end at corner (scaffolding level: 15th floor)	3/10/08	3.55	Silica	NIOSH 7500 XRD	EMSL	3/11/08	< 1	No	No	
SILICA-ST1-3/11/08	040805827-0001	Southwest Area (sidewalk bridge level)	3/11/08	3.69	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST2-3/11/08	040805827-0002	Southeast Area (sidewalk bridge level)	3/11/08	3.73	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST4-3/11/08	040805827-0003	Northwest Area (street-level)	3/11/08	3.5	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST5-3/11/08	040805827-0004	Firehouse #10 (roof level)	3/11/08	3.56	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST10-3/11/08	040805827-0005	North Side Sidewalk Bridge	3/11/08	3.23	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 2	No	No	
SILICA-ST11-3/11/08	040805827-0006	90 Trinity Place (roof level)	3/11/08	3.66	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST12-3/11/08	040805827-0007	110 Greenwich Street (roof level)	3/11/08	3.64	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST13-3/11/08	040805827-0008	Marriott Hotel, 38th Floor (roof level)	3/11/08	3.57	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST14(15th) -3/11/08	040805827-0009	West Face - South end at corner (scaffolding level: 15th floor)	3/11/08	3.7	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST15(15th) -3/11/08	040805827-0010	South Face - East end at corner (scaffolding level: 15th floor)	3/11/08	3.52	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST16(15th) -3/11/08	040805827-0011	East Face - North end at corner (scaffolding level: 15th floor)	3/11/08	3.52	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	
SILICA-ST17(15th) -3/11/08	040805827-0012	North Face - West end at corner (scaffolding level: 15th floor)	3/11/08	3.5	Silica	NIOSH 7500 XRD	EMSL	3/12/08	< 1	No	No	

Note:

1. The silica sample at Station 14 (West Face - South end at corner [scaffolding level: 15th floor]) on March 10, 2008 was not available for analysis on account of pump failure.