

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-3/10/10	041004964-0001	Southwest Area (sidewalk bridge level)	3/10/10	3.64	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	
SILICA-ST2-3/10/10	041004964-0002	Southeast Area (sidewalk bridge level)	3/10/10	3.59	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	
SILICA-ST4-3/10/10	041004964-0003	Northwest Area (street-level)	3/10/10	3.59	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	
SILICA-ST5-3/10/10	041004964-0004	Firehouse #10 (roof level)	3/10/10	3.72	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 5	No	No	
SILICA-ST11-3/10/10	041004964-0006	90 Trinity Place (roof level)	3/10/10	3.59	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	
SILICA-ST12-3/10/10	041004964-0007	110 Greenwich Street (roof level)	3/10/10	3.63	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	
SILICA-ST13-3/10/10	041004964-0008	Marriott Hotel, 38th Floor (roof level)	3/10/10	3.55	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	
SILICA-ST20-3/10/10	041004964-0005	Northeast Area, Sidewalk Bridge	3/10/10	3.54	Silica	NIOSH 7500 XRD	EMSL	3/12/10	< 1	No	No	