

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Air Quality Levels	Site Specific Trigger Levels	
									10			
SILICA-ST1-3/15/07	040705329-0001	Southwest Area (sidewalk bridge level)	3/15/07	3.55	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST2-3/15/07	040705329-0002	Southeast Area (sidewalk bridge level)	3/15/07	3.67	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST4-3/15/07	040705329-0003	Northwest Area (street-level)	3/15/07	3.62	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST5-3/15/07	040705329-0004	Firehouse #10 (roof level)	3/15/07	3.57	Silica	NIOSH 7500 XRD	EMSL	3/16/07	3	No	No	
SILICA-ST10-3/15/07	040705329-0005	North Side Sidewalk Bridge	3/15/07	3.44	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST100-3/15/07	040705329-0013	Station 10 Field Duplicate	3/15/07	3.66	Silica	NIOSH 7500 XRD	EMSL	3/16/07	3	No	No	
SILICA-ST11-3/15/07	040705329-0006	90 Trinity Place (roof level)	3/15/07	3.65	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST12-3/15/07	040705329-0007	110 Greenwich Street (roof level)	3/15/07	3.97	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST13-3/15/07	040705329-0008	Marriott Hotel, 38th Floor (roof level)	3/15/07	3.59	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST14-3/15/07 (30th)	040705329-0009	West Face - South end at corner (scaffolding level: 30th floor)	3/15/07	3.5	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST15-3/15/07 (30th)	040705329-0010	South Face - East end at corner (scaffolding level: 30th floor)	3/15/07	3.4	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	
SILICA-ST16-3/15/07 (30th)	040705329-0011	East Face - North end at corner (scaffolding level: 30th floor)	3/15/07	3.5	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 6	No	No	
SILICA-ST17-3/15/07 (30th)	040705329-0012	North Face - West end at corner (scaffolding level: 30th floor)	3/15/07	3.51	Silica	NIOSH 7500 XRD	EMSL	3/16/07	< 1	No	No	