

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>10</b>			
									<b>10</b>			
SILICA-ST1-3/19/07	040705563-0001	Southwest Area (sidewalk bridge level)	3/19/07	3.62	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST2-3/19/07	040705563-0002	Southeast Area (sidewalk bridge level)	3/19/07	3.53	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST4-3/19/07	040705563-0003	Northwest Area (street-level)	3/19/07	3.38	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST5-3/19/07	040705563-0004	Firehouse #10 (roof level)	3/19/07	3.58	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST10-3/19/07	040705563-0005	North Side Sidewalk Bridge	3/19/07	3.5	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST11-3/19/07	040705563-0006	90 Trinity Place (roof level)	3/19/07	3.57	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST12-3/19/07	040705563-0007	110 Greenwich Street (roof level)	3/19/07	3.45	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST13-3/19/07	040705563-0008	Marriott Hotel, 38th Floor (roof level)	3/19/07	3.57	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST15(30th) -3/19/07	040705563-0009	South Face - East end at corner (scaffolding level: 30th floor)	3/19/07	3.64	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST16(30th) -3/19/07	040705563-0010	East Face - North end at corner (scaffolding level: 30th floor)	3/19/07	3.64	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST17(30th) -3/19/07	040705563-0011	North Face - West end at corner (scaffolding level: 30th floor)	3/19/07	3.64	Silica	NIOSH 7500 XRD	EMSL	3/20/07	< 1	No	No	
SILICA-ST1-3/20/07	040705680-0001	Southwest Area (sidewalk bridge level)	3/20/07	3.71	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST2-3/20/07	040705680-0002	Southeast Area (sidewalk bridge level)	3/20/07	3.66	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST4-3/20/07	040705680-0003	Northwest Area (street-level)	3/20/07	3.42	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST5-3/20/07	040705680-0004	Firehouse #10 (roof level)	3/20/07	3.61	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST10-3/20/07	040705680-0005	North Side Sidewalk Bridge	3/20/07	3.6	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST11-3/20/07	040705680-0006	90 Trinity Place (roof level)	3/20/07	3.5	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST12-3/20/07	040705680-0007	110 Greenwich Street (roof level)	3/20/07	3.56	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST13-3/20/07	040705680-0008	Marriott Hotel, 38th Floor (roof level)	3/20/07	3.58	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST14(30th) -3/20/07	040705680-0009	West Face - South end at corner (scaffolding level: 30th floor)	3/20/07	3.68	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST15(30th) -3/20/07	040705680-0010	South Face - East end at corner (scaffolding level: 30th floor)	3/20/07	3.57	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST16(30th) -3/20/07	040705680-0011	East Face - North end at corner (scaffolding level: 30th floor)	3/20/07	3.63	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	
SILICA-ST17(30th) -3/20/07	040705680-0012	North Face - West end at corner (scaffolding level: 30th floor)	3/20/07	3.63	Silica	NIOSH 7500 XRD	EMSL	3/21/07	< 1	No	No	

Note:

1. Silica sample at Station 14 (West Face - South end at corner [scaffolding level: 30th floor]) on March 19, 2007 was not available for analysis on account of sample damage.