

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>10</b>			
									<b>10</b>			
SILICA-ST1-3/21/06	040605396-0001	Southwest Area (sidewalk bridge level)	3/21/06	3.6	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST2-3/21/06	040605396-0002	Southeast Area (sidewalk bridge level)	3/21/06	3.61	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST4-3/21/06	040605396-0003	Northwest Area (street-level)	3/21/06	3.62	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST5-3/21/06	040605396-0004	Firehouse #10 (roof level)	3/21/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST10-3/21/06	040605396-0005	North Side Sidewalk Bridge	3/21/06	3.62	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST11-3/21/06	040605396-0006	90 Trinity Place (roof level)	3/21/06	3.63	Silica	NIOSH 7500 XRD	EMSL	3/22/06	2	No	No	
SILICA-ST12-3/21/06	040605396-0007	110 Greenwich Street (roof level)	3/21/06	3.64	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST13-3/21/06	040605396-0008	Marriott Hotel, 38th Floor (roof level)	3/21/06	3.45	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST14-3/21/06	040605396-0009	West Face - South end at corner (scaffolding level)	3/21/06	3.57	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST15-3/21/06	040605396-0010	South Face - East end at corner (scaffolding level)	3/21/06	3.6	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST16-3/21/06	040605396-0011	East Face - North end at corner (scaffolding level)	3/21/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	
SILICA-ST17-3/21/06	040605396-0012	North Face - West end at corner (scaffolding level)	3/21/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/22/06	< 1	No	No	