

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-4/5/10	041006951-0001	Southwest Area (sidewalk bridge level)	4/5/10	3.62	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST2-4/5/10	041006951-0002	Southeast Area (sidewalk bridge level)	4/5/10	3.66	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST4-4/5/10	041006951-0003	Northwest Area (street-level)	4/5/10	3.64	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST5-4/5/10	041006951-0004	Firehouse #10 (roof level)	4/5/10	3.56	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST11-4/5/10	041006951-0006	90 Trinity Place (roof level)	4/5/10	3.46	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST12-4/5/10	041006951-0007	110 Greenwich Street (roof level)	4/5/10	3.73	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST13-4/5/10	041006951-0008	Marriott Hotel, 38th Floor (roof level)	4/5/10	3.56	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	
SILICA-ST20-4/5/10	041006951-0005	Northeast Area, Sidewalk Bridge	4/5/10	3.59	Silica	NIOSH 7500 XRD	EMSL	4/7/10	< 1	No	No	

Note:
1. The silica results are not available for April 3 and 4, 2010 since no sampling was conducted on these days due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.