

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-4/11/06	040606882-0001	Southwest Area (sidewalk bridge level)	4/11/06	3.57	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST2-4/11/06	040606882-0002	Southeast Area (sidewalk bridge level)	4/11/06	3.58	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST4-4/11/06	040606882-0003	Northwest Area (street-level)	4/11/06	3.49	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST5-4/11/06	040606882-0004	Firehouse #10 (roof level)	4/11/06	3.6	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST10-4/11/06	040606882-0005	North Side Sidewalk Bridge	4/11/06	3.53	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST11-4/11/06	040606882-0006	90 Trinity Place (roof level)	4/11/06	3.58	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST12-4/11/06	040606882-0007	110 Greenwich Street (roof level)	4/11/06	3.6	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST13-4/11/06	040606882-0008	Marriott Hotel, 38th Floor (roof level)	4/11/06	3.49	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST14-4/11/06	040606882-0009	West Face - South end at corner (scaffolding level)	4/11/06	3.53	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST15-4/11/06	040606882-0010	South Face - East end at corner (scaffolding level)	4/11/06	3.58	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST16-4/11/06	040606882-0011	East Face - North end at corner (scaffolding level)	4/11/06	3.54	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	
SILICA-ST17-4/11/06	040606882-0012	North Face - West end at corner (scaffolding level)	4/11/06	3.55	Silica	NIOSH 7500 XRD	EMSL	4/12/06	< 1	No	No	