

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-5/2/06	040608536-0001	Southwest Area (sidewalk bridge level)	5/2/06	3.59	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST2-5/2/06	040608536-0002	Southeast Area (sidewalk bridge level)	5/2/06	3.58	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST4-5/2/06	040608536-0003	Northwest Area (street-level)	5/2/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 6	No	No	
SILICA-ST5-5/2/06	040608536-0004	Firehouse #10 (roof level)	5/2/06	3.58	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST10-5/2/06	040608536-0005	North Side Sidewalk Bridge	5/2/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST11-5/2/06	040608536-0006	90 Trinity Place (roof level)	5/2/06	3.59	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST12-5/2/06	040608536-0007	110 Greenwich Street (roof level)	5/2/06	3.61	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST13-5/2/06	040608536-0008	Marriott Hotel, 38th Floor (roof level)	5/2/06	3.62	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST14-5/2/06	040608536-0009	West Face - South end at corner (scaffolding level)	5/2/06	3.56	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST15-5/2/06	040608536-0010	South Face - East end at corner (scaffolding level)	5/2/06	3.56	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST16-5/2/06	040608536-0011	East Face - North end at corner (scaffolding level)	5/2/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	
SILICA-ST17-5/2/06	040608536-0012	North Face - West end at corner (scaffolding level)	5/2/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/3/06	< 1	No	No	