

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-5/9/06	040609148-0001	Southwest Area (sidewalk bridge level)	5/9/06	3.6	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST2-5/9/06	040609148-0002	Southeast Area (sidewalk bridge level)	5/9/06	3.6	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST4-5/9/06	040609148-0003	Northwest Area (street-level)	5/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST5-5/9/06	040609148-0004	Firehouse #10 (roof level)	5/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST10-5/9/06	040609148-0005	North Side Sidewalk Bridge	5/9/06	3.56	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST11-5/9/06	040609148-0006	90 Trinity Place (roof level)	5/9/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST12-5/9/06	040609148-0007	110 Greenwich Street (roof level)	5/9/06	3.54	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST13-5/9/06	040609148-0008	Marriott Hotel, 38th Floor (roof level)	5/9/06	3.52	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST14-5/9/06	040609148-0009	West Face - South end at corner (scaffolding level)	5/9/06	3.51	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST15-5/9/06	040609148-0010	South Face - East end at corner (scaffolding level)	5/9/06	3.46	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST16-5/9/06	040609148-0011	East Face - North end at corner (scaffolding level)	5/9/06	3.42	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST17-5/9/06	040609148-0012	North Face - West end at corner (scaffolding level)	5/9/06	3.53	Silica	NIOSH 7500 XRD	EMSL	5/10/06	< 1	No	No	
SILICA-ST1-5/10/06	040609237-0001	Southwest Area (sidewalk bridge level)	5/10/06	3.6	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST2-5/10/06	040609237-0002	Southeast Area (sidewalk bridge level)	5/10/06	3.59	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST4-5/10/06	040609237-0003	Northwest Area (street-level)	5/10/06	3.58	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST5-5/10/06	040609237-0004	Firehouse #10 (roof level)	5/10/06	3.63	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST10-5/10/06	040609237-0005	North Side Sidewalk Bridge	5/10/06	3.62	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST11-5/10/06	040609237-0006	90 Trinity Place (roof level)	5/10/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST12-5/10/06	040609237-0007	110 Greenwich Street (roof level)	5/10/06	3.6	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST13-5/10/06	040609237-0008	Marriott Hotel, 38th Floor (roof level)	5/10/06	3.6	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST14-5/10/06	040609237-0009	West Face - South end at corner (scaffolding level)	5/10/06	3.61	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST15-5/10/06	040609237-0010	South Face - East end at corner (scaffolding level)	5/10/06	3.64	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST16-5/10/06	040609237-0011	East Face - North end at corner (scaffolding level)	5/10/06	3.61	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	
SILICA-ST17-5/10/06	040609237-0012	North Face - West end at corner (scaffolding level)	5/10/06	3.61	Silica	NIOSH 7500 XRD	EMSL	5/11/06	< 1	No	No	