

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									10			
SILICA-ST1-5/20/09	040912704-0001	Southwest Area (sidewalk bridge level)	5/20/09	3.74	Silica	NIOSH 7500 XRD	EMSL	5/21/09	2	No	No	
SILICA-ST2-5/20/09	040912704-0002	Southeast Area (sidewalk bridge level)	5/20/09	3.73	Silica	NIOSH 7500 XRD	EMSL	5/21/09	5	No	No	
SILICA-ST4-5/20/09	040912704-0003	Northwest Area (street-level)	5/20/09	3.56	Silica	NIOSH 7500 XRD	EMSL	5/21/09	1	No	No	
SILICA-ST5-5/20/09	040912704-0004	Firehouse #10 (roof level)	5/20/09	3.5	Silica	NIOSH 7500 XRD	EMSL	5/21/09	2	No	No	
SILICA-ST10-5/20/09	040912704-0005	North Side Sidewalk Bridge	5/20/09	3.56	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST11-5/20/09	040912704-0006	90 Trinity Place (roof level)	5/20/09	3.66	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 5	No	No	
SILICA-ST12-5/20/09	040912704-0007	110 Greenwich Street (roof level)	5/20/09	3.55	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST13-5/20/09	040912704-0008	Marriott Hotel, 38th Floor (roof level)	5/20/09	3.53	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST14(15th)-5/20/09	040912704-0009	West Face - South end at corner (scaffolding level: 15th floor)	5/20/09	3.72	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST15(15th)-5/20/09	040912704-0010	South Face - East end at corner (scaffolding level: 15th floor)	5/20/09	3.64	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST16(15th)-5/20/09	040912704-0011	East Face - North end at corner (scaffolding level: 15th floor)	5/20/09	3.55	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST17(15th)-5/20/09	040912704-0012	North Face - West end at corner (scaffolding level: 15th floor)	5/20/09	3.62	Silica	NIOSH 7500 XRD	EMSL	5/21/09	< 1	No	No	
SILICA-ST100-5/20/09	040912704-0013	Station 10 Field Duplicate	5/20/09	3.46	Silica	NIOSH 7500 XRD	EMSL	5/21/09	2	No	No	