

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	<b>Exceeds Target Air Quality Levels</b>	<b>Exceeds EPA Site Specific Trigger Levels</b>	
									<b>10</b>			
SILICA-ST1-5/31/08	040813454-0001	Southwest Area (sidewalk bridge level)	5/31/08	3.57	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST2-5/31/08	040813454-0002	Southeast Area (sidewalk bridge level)	5/31/08	3.4	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST4-5/31/08	040813454-0003	Northwest Area (street-level)	5/31/08	3.55	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST5-5/31/08	040813454-0004	Firehouse #10 (roof level)	5/31/08	3.54	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST10-5/31/08	040813454-0005	North Side Sidewalk Bridge	5/31/08	3.67	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST11-5/31/08	040813454-0006	90 Trinity Place (roof level)	5/31/08	3.56	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST12-5/31/08	040813454-0007	110 Greenwich Street (roof level)	5/31/08	3.42	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST13-5/31/08	040813454-0008	Marriott Hotel, 38th Floor (roof level)	5/31/08	3.56	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST14(15th) -5/31/08	040813454-0009	West Face - South end at corner (scaffolding level: 15th floor)	5/31/08	3.58	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST15(15th) -5/31/08	040813454-0010	South Face - East end at corner (scaffolding level: 15th floor)	5/31/08	3.5	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST16(15th) -5/31/08	040813454-0011	East Face - North end at corner (scaffolding level: 15th floor)	5/31/08	3.55	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	
SILICA-ST17(15th) -5/31/08	040813454-0012	North Face - West end at corner (scaffolding level: 15th floor)	5/31/08	3.51	Silica	NIOSH 7500 XRD	EMSL	6/3/08	< 1	No	No	