

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
SILICA-ST1-6/20/09	040915619-0001	Southwest Area (sidewalk bridge level)	6/20/09	3.61	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST2-6/20/09	040915619-0002	Southeast Area (sidewalk bridge level)	6/20/09	3.56	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST4-6/20/09	040915619-0003	Northwest Area (street-level)	6/20/09	3.67	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST5-6/20/09	040915619-0004	Firehouse #10 (roof level)	6/20/09	3.6	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST10-6/20/09	040915619-0005	North Side Sidewalk Bridge	6/20/09	3.57	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST11-6/20/09	040915619-0006	90 Trinity Place (roof level)	6/20/09	3.58	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST12-6/20/09	040915619-0007	110 Greenwich Street (roof level)	6/20/09	3.61	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST13-6/20/09	040915619-0008	Marriott Hotel, 38th Floor (roof level)	6/20/09	3.7	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST1-6/21/09	040915618-0001	Southwest Area (sidewalk bridge level)	6/21/09	3.63	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST2-6/21/09	040915618-0002	Southeast Area (sidewalk bridge level)	6/21/09	3.52	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST4-6/21/09	040915618-0003	Northwest Area (street-level)	6/21/09	3.59	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST5-6/21/09	040915618-0004	Firehouse #10 (roof level)	6/21/09	3.63	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST10-6/21/09	040915618-0005	North Side Sidewalk Bridge	6/21/09	3.57	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST11-6/21/09	040915618-0006	90 Trinity Place (roof level)	6/21/09	3.58	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST12-6/21/09	040915618-0007	110 Greenwich Street (roof level)	6/21/09	3.69	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST13-6/21/09	040915618-0008	Marriott Hotel, 38th Floor (roof level)	6/21/09	3.67	Silica	NIOSH 7500 XRD	EMSL	6/22/09	< 1	No	No	
SILICA-ST1-6/22/09	040915588-0001	Southwest Area (sidewalk bridge level)	6/22/09	3.79	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	
SILICA-ST2-6/22/09	040915588-0002	Southeast Area (sidewalk bridge level)	6/22/09	3.77	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	
SILICA-ST4-6/22/09	040915588-0003	Northwest Area (street-level)	6/22/09	3.71	Silica	NIOSH 7500 XRD	EMSL	6/23/09	4	No	No	
SILICA-ST5-6/22/09	040915588-0004	Firehouse #10 (roof level)	6/22/09	3.48	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	
SILICA-ST10-6/22/09	040915588-0005	North Side Sidewalk Bridge	6/22/09	3.74	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	
SILICA-ST11-6/22/09	040915588-0006	90 Trinity Place (roof level)	6/22/09	3.66	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	
SILICA-ST12-6/22/09	040915588-0007	110 Greenwich Street (roof level)	6/22/09	3.65	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	
SILICA-ST13-6/22/09	040915588-0008	Marriott Hotel, 38th Floor (roof level)	6/22/09	3.58	Silica	NIOSH 7500 XRD	EMSL	6/23/09	< 1	No	No	