

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-6/23/10	041013537-0001	Southwest Area (sidewalk bridge level)	6/23/10	3.64	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST2-6/23/10	041013537-0002	Southeast Area (sidewalk bridge level)	6/23/10	3.51	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST4-6/23/10	041013537-0003	Northwest Area (street-level)	6/23/10	3.54	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST5-6/23/10	041013537-0004	Firehouse #10 (roof level)	6/23/10	3.59	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST11-6/23/10	041013537-0006	90 Trinity Place (roof level)	6/23/10	3.66	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST12-6/23/10	041013537-0007	110 Greenwich Street (roof level)	6/23/10	3.5	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST20-6/23/10	041013537-0005	Northeast Area, Sidewalk Bridge	6/23/10	3.63	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST200-6/23/10	041013537-0009	Station 20 Field Duplicate	6/23/10	3.62	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	
SILICA-ST21-6/23/10	041013537-0008	Marriott Hotel, 4th Floor	6/23/10	3.51	Silica	NIOSH 7500 XRD	EMSL	6/25/10	< 1	No	No	