

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	<b>Exceeds Target Air Quality Levels</b>	<b>Exceeds EPA Site Specific Trigger Levels</b>	
									<b>10</b>			
SILICA-ST1-7/10/07	040715964-0001	Southwest Area (sidewalk bridge level)	7/10/07	3.48	Silica	NIOSH 7500 XRD	EMSL	7/11/07	2	No	No	
SILICA-ST2-7/10/07	040715964-0002	Southeast Area (sidewalk bridge level)	7/10/07	3.4	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	
SILICA-ST4-7/10/07	040715964-0003	Northwest Area (street-level)	7/10/07	3.6	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	
SILICA-ST5-7/10/07	040715964-0004	Firehouse #10 (roof level)	7/10/07	3.68	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	
SILICA-ST10-7/10/07	040715964-0005	North Side Sidewalk Bridge	7/10/07	3.68	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	
SILICA-ST11-7/10/07	040715964-0006	90 Trinity Place (roof level)	7/10/07	3.33	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 2	No	No	
SILICA-ST12-7/10/07	040715964-0007	110 Greenwich Street (roof level)	7/10/07	3.47	Silica	NIOSH 7500 XRD	EMSL	7/11/07	2	No	No	
SILICA-ST13-7/10/07	040715964-0008	Marriott Hotel, 38th Floor (roof level)	7/10/07	3.58	Silica	NIOSH 7500 XRD	EMSL	7/11/07	1	No	No	
SILICA-ST14(24th) -7/10/07	040715964-0009	West Face - South end at corner (scaffolding level: 24th floor)	7/10/07	3.53	Silica	NIOSH 7500 XRD	EMSL	7/11/07	1	No	No	
SILICA-ST15(24th) -7/10/07	040715964-0010	South Face - East end at corner (scaffolding level: 24th floor)	7/10/07	3.46	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	
SILICA-ST16(24th) -7/10/07	040715964-0011	East Face - North end at corner (scaffolding level: 24th floor)	7/10/07	3.56	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	
SILICA-ST17(24th) -7/10/07	040715964-0012	North Face - West end at corner (scaffolding level: 24th floor)	7/10/07	3.52	Silica	NIOSH 7500 XRD	EMSL	7/11/07	< 1	No	No	