

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-7/15/08	040818002-0001	Southwest Area (sidewalk bridge level)	7/15/08	3.67	Silica	NIOSH 7500 XRD	EMSL	7/16/08	2	No	No	
SILICA-ST2-7/15/08	040818002-0002	Southeast Area (sidewalk bridge level)	7/15/08	3.82	Silica	NIOSH 7500 XRD	EMSL	7/16/08	1	No	No	
SILICA-ST4-7/15/08	040818002-0003	Northwest Area (street-level)	7/15/08	3.68	Silica	NIOSH 7500 XRD	EMSL	7/16/08	< 1	No	No	
SILICA-ST5-7/15/08	040818002-0004	Firehouse #10 (roof level)	7/15/08	3.52	Silica	NIOSH 7500 XRD	EMSL	7/16/08	< 1	No	No	
SILICA-ST10-7/15/08	040818002-0005	North Side Sidewalk Bridge	7/15/08	3.68	Silica	NIOSH 7500 XRD	EMSL	7/16/08	3	No	No	
SILICA-ST11-7/15/08	040818002-0006	90 Trinity Place (roof level)	7/15/08	3.56	Silica	NIOSH 7500 XRD	EMSL	7/16/08	1	No	No	
SILICA-ST12-7/15/08	040818002-0007	110 Greenwich Street (roof level)	7/15/08	3.63	Silica	NIOSH 7500 XRD	EMSL	7/16/08	1	No	No	
SILICA-ST13-7/15/08	040818002-0008	Marriott Hotel, 38th Floor (roof level)	7/15/08	3.6	Silica	NIOSH 7500 XRD	EMSL	7/16/08	< 1	No	No	
SILICA-ST14(15th) -7/15/08	040818002-0009	West Face - South end at corner (scaffolding level: 15th floor)	7/15/08	3.61	Silica	NIOSH 7500 XRD	EMSL	7/16/08	< 1	No	No	
SILICA-ST16(15th) -7/15/08	040818002-0011	East Face - North end at corner (scaffolding level: 15th floor)	7/15/08	3.69	Silica	NIOSH 7500 XRD	EMSL	7/16/08	< 1	No	No	
SILICA-ST17(15th) -7/15/08	040818002-0012	North Face - West end at corner (scaffolding level: 15th floor)	7/15/08	3.56	Silica	NIOSH 7500 XRD	EMSL	7/16/08	< 1	No	No	
SILICA-ST1-7/16/08	040818168-0001	Southwest Area (sidewalk bridge level)	7/16/08	3.61	Silica	NIOSH 7500 XRD	EMSL	7/17/08	2	No	No	
SILICA-ST2-7/16/08	040818168-0002	Southeast Area (sidewalk bridge level)	7/16/08	3.82	Silica	NIOSH 7500 XRD	EMSL	7/17/08	3	No	No	
SILICA-ST4-7/16/08	040818168-0003	Northwest Area (street-level)	7/16/08	3.66	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST5-7/16/08	040818168-0004	Firehouse #10 (roof level)	7/16/08	3.53	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST10-7/16/08	040818168-0005	North Side Sidewalk Bridge	7/16/08	3.58	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST11-7/16/08	040818168-0006	90 Trinity Place (roof level)	7/16/08	3.55	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST12-7/16/08	040818168-0007	110 Greenwich Street (roof level)	7/16/08	3.61	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST13-7/16/08	040818168-0008	Marriott Hotel, 38th Floor (roof level)	7/16/08	3.64	Silica	NIOSH 7500 XRD	EMSL	7/17/08	4	No	No	
SILICA-ST14(15th) -7/16/08	040818168-0009	West Face - South end at corner (scaffolding level: 15th floor)	7/16/08	3.73	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST15(15th) -7/16/08	040818168-0010	South Face - East end at corner (scaffolding level: 15th floor)	7/16/08	3.19	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST16(15th) -7/16/08	040818168-0011	East Face - North end at corner (scaffolding level: 15th floor)	7/16/08	3.4	Silica	NIOSH 7500 XRD	EMSL	7/17/08	< 1	No	No	
SILICA-ST17(15th) -7/16/08	040818168-0012	North Face - West end at corner (scaffolding level: 15th floor)	7/16/08	3.62	Silica	NIOSH 7500 XRD	EMSL	7/17/08	2	No	No	

Note:

1. Silica sample at Station 15 (South Face - East end at corner [scaffolding level: 15th floor]) on July 15, 2008 was not available for analysis on account of laboratory error.